

Edgetek™ AT Acetal (POM) Compounds

Problem	Cause	Solution
Weld Lines	Melt front temp are too low	<ol style="list-style-type: none"> 1. Increase pack and hold pressure 2. Increase melt temperature 3. Increase vent width and locations 4. Increase injection rate 5. Increase mold temperature
	Mold design	<ol style="list-style-type: none"> 1. Reduce injection rate 2. Increase gate size 3. Perform short shots to determine fill pattern and verify proper vent location 4. Add vents and/or false ejector pin 5. Move gate location
Flash	Injection pressure too high	<ol style="list-style-type: none"> 1. Decrease injection pressure 2. Increase clamp pressure 3. Decrease injection rate 4. Increase transfer position
	Excess material volume	<ol style="list-style-type: none"> 1. Decrease pack pressure 2. Reduce shot size 3. Decrease injection rate
	Melt and/or mold too hot	<ol style="list-style-type: none"> 1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature 3. Decrease screw speed
Sink Marks	Part geometry too thick	<ol style="list-style-type: none"> 1. Reduce wall thickness 2. Reduce rib thickness
	Melt too hot	<ol style="list-style-type: none"> 1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature
	Insufficient material volume	<ol style="list-style-type: none"> 1. Increase shot size 2. Increase injection rate 3. Increase packing pressure 4. Increase gate size
Burning	Melt and/or mold too hot	<ol style="list-style-type: none"> 1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature 3. Reduce injection rate 4. Consult PolyOne for specific grade of Edgetek AT compounds
	Mold design	<ol style="list-style-type: none"> 1. Clean, widen and increase number of vents 2. Increase gate diameter or number of gates.
Incomplete Fill	Melt and/or mold too hot	<ol style="list-style-type: none"> 1. Increase nozzle and barrel temperatures 2. Increase mold temperature 3. Increase pack and hold pressure 4. Increase injection rate 5. Check thermocouples and heater bands
	Mold design	<ol style="list-style-type: none"> 1. Enlarge or widen vents and increase number of vents 2. Check that vents are unplugged 3. Check that gates are unplugged 4. Enlarge gates and/or runners 5. Perform short shots to determine fill pattern and verify proper vent location 6. Increase wall thickness to move gas trap to parting line
	Shot size	<ol style="list-style-type: none"> 1. Increase shot size 2. Increase cushion
Brittleness	Low melt temperature	<ol style="list-style-type: none"> 1. Increase melt temperature 2. Increase injection rate 3. Measure melt temperature with pyrometer
	Degraded/Overheated material	<ol style="list-style-type: none"> 1. Decrease back pressure 2. Decrease melt temperature 3. Use smaller barrel/excessive residence time
	Gate location and/or size	<ol style="list-style-type: none"> 1. Relocate gate to nonstress area 2. Increase gate size to allow higher flow rate
Sticking in Mold	Cavities are overpacked	<ol style="list-style-type: none"> 1. Reduce injection rate 2. Reduce pack and hold pressure 3. Reduce nozzle and barrel temperatures 4. Reduce mold temperature 5. Increase cooling time

Problem	Cause	Solution
Sticking in Mold	Mold design	1. Increase draft angle
	Part is too hot	1. Decrease nozzle and barrel temperatures 2. Decrease mold temperature 3. Increase cooling time
Warp	Excessive orientation	1. Increase cooling time 2. Increase melt temperature 3. Reduce injection pressure and injection rate
	Mold design	1. Increase number of gates
Uneven Surface Appearance	Melt temperature too low	1. Increase melt temperature 2. Increase mold temperature 3. Increase injection speed
	Insufficient packing	1. Increase pack and hold pressure and time 2. Increase shot size
Excessive Shrink	Too much orientation	1. Increase packing time and pressure 2. Increase hold pressure 3. Reduce melt temperature 4. Reduce mold temperature 5. Reduce injection speed 6. Reduce screw rpm 7. Increase venting 8. Increase cooling time
	Too little orientation	1. Decrease packing time and pressure 2. Decrease hold pressure 3. Increase melt temperature 4. Increase mold temperature 5. Increase injection speed 6. Increase screw rpm 7. Decrease cooling time
Color Streaks	Incomplete color dispersion	1. Increase back pressure 2. Verify color concentrate compatibility 3. Reduce rear zone temperature 4. Increase injection rate

CONTACT INFORMATION

Europe

Germany – Gaggenau
+49 (0) 7225 680 20
Spain – Barbastro
+34 (0) 97431 0314
Turkey – Istanbul
+90 (0) 212 549 2241

Americas

U.S. – Avon Lake, Ohio
+1 440 930 1000

Asia

China – DongGuan
+86 (0) 769 8587 8800
China – Shenzhen
+86 (0) 755 2969 2888
India – Mumbai
+91 9820 194 220
Singapore
+65 (0) 6861 9325



*Beyond Polymers.
Better Business Solutions.™*

www.polyone.com

PolyOne Americas

33587 Walker Road
Avon Lake, OH 44012
U.S.A.
Tel.: +1 440 930 1000

PolyOne Asia

Guoshoujing Road No. 88
Z.J Hi-Tech Park, Pudong
Shanghai, 201203, China
Tel.: +86 (0) 21 5080 1188

PolyOne Europe

Rue Melville Wilson 2
5330 Assesse, Belgium
Tel.: +32 (0) 83 660 211

Copyright © 2007, PolyOne Corporation. PolyOne makes no representations, guarantees, or warranties of any kind with respect to the Information contained in this document about its accuracy, suitability for particular applications, or the results obtained or obtainable using the information. Some of the Information arises from laboratory work with small-scale equipment which may not provide a reliable indication of performance or properties obtained or obtainable on larger-scale equipment. Values reported as “typical” or stated without a range do not state minimum or maximum properties; consult your sales representative for property ranges and min/max specifications. Processing conditions can cause material properties to shift from the values stated in the Information. PolyOne makes no warranties or guarantees respecting suitability of either PolyOne’s products or the Information for your process or end-use application. You have the responsibility to conduct full-scale end-product performance testing to determine suitability in your application, and you assume all risk and liability arising from your use of the Information and/or use or handling of any product. POLYONE MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, either with respect to the Information or products reflected by the Information. This data sheet shall NOT operate as permission, recommendation, or inducement to practice any patented invention without permission of the patent owner.